

- ▶ Pressen Sie Ihr Textil 3-5 Sekunden vor, um die textileigene Feuchtigkeit und Falten aus dem Stoff zu entfernen.
- ▶ Platzieren Sie Ihr Transfer mit dem Motiv nach unten auf dem Textil & decken Sie es mit einem Abdeckbogen ab.
- ▶ Drucken Sie das Motiv laut Andruckanleitung an.
- ▶ Danach ziehen Sie das Trägerpapier wie angegeben ab.

Ultra Color™ Transfer

Baumwolle,
nicht sublimationsgefärbtes Polyester,
Baumwolle / Polyester-Mischungen

Sublimationsgefärbtes Polyester
(mit Subli-Blocker!)

Temperatur: 160° C – 165° C

Temperatur: 160° C – 165° C

Zeit: 20 Sek.

Zeit: 20 Sek.

Druck: Mittel / Hoch
(#4 – 7 bei Hotronix®)

Druck: Mittel / Hoch
(#4 – 7 bei Hotronix®)

Trägerpapier: Kalt abziehen

Trägerpapier: Kalt abziehen

BITTE BEACHTEN BEIM BEDRUCKEN VON SUBLIMATIONSGEFÄRBTEN POLYESTER

Bitte bestellen Sie zu diesen Transfers zusätzlich unseren Sublimationsblocker, sobald Sie sublimationsgefärbte Polyester Textilien bedrucken möchten, um ein Durchfärben der Sublimationsfarbe auf Ihr Transfer zu verhindern.

Im Zweifel führen Sie bitte einen Andrucktest durch, da wir ein 100%iges Blocken der Sublimationsfarbe auf Grund der unterschiedlichen, am Markt erhältlichen Qualitäten leider nicht immer gewährleisten können.

WASCHBARKEIT

Baumwolle,
nicht sublimationsgefärbtes Polyester
Baumwolle / Polyester-Mischungen

Sublimationsgefärbtes Polyester
(mit Subli-Blocker!)

Bis **40° C** waschbar

Bis **40° C** waschbar

Bitte auf die Waschbarkeit des Textils achten. Verwenden Sie kein Flüssigwaschmittel, Weichspüler.
Nicht für die chemische Reinigung bzw. Trockner geeignet. Von links waschen und bügeln.

- ▶ Pre press your garment between 3-5 seconds to remove any creases or moisture.
- ▶ Lay transfer with motif down on your textile and cover with release paper or your teflon sheet.
- ▶ Apply for a few seconds, exact parameters you will see down.
- ▶ Remove paper carrier.

Ultra Color™ Transfer

Cotton,
non-sublimation dyed polyester,
Cotton / polyester blends

Sublimation dyed polyester
(with Subli-Blocker!)

Temperature: 160° C – 165° C

Temperature: 160° C – 165° C

Time: 20 Sec.

Time: 20 Sec.

Pressure: Medium / High
(#4 – 7 bei Hotronix®)

Pressure: Medium / High
(#4 – 7 bei Hotronix®)

Paper carrier: peel cold

Paper carrier: peel cold

PLEASE NOTE WHEN PRINTING ON SUBLIMATION DYED POLYESTER

Polyester garments are often dyed with sublimation inks, we always recommend previous heat application and wash tests. At first washing the surplus ink might be bleeding. For such garments, we cannot guarantee colour fastness of the transfers. Please add here a sublimation-colour when you order the prints for these textiles and make applications test before printing.

WASHABILITY

Cotton,
non-sublimation dyed polyester,
Cotton / polyester blends

Sublimation dyed polyester
(with Subli-Blocker!)

Washable up to **40° C**

Washable up to **40° C**

Please pay attention to the washability of the textile. Do not use liquid detergent, fabric softener. Not suitable for dry cleaning or drying. Wash and iron inside out.